

## End-of-Life (EOL) Products

This is a list of the obsoleted products at i5 Communications.

| Discontinued Product                              | Replacement Product      | Notes  |
|---|--------------------------|--|
| iSG4F   | iSG18GFP                 | Effective Nov. 26 <sup>th</sup> , 2019   |
| iROC (stand-alone)                                | iROC module in RAPTOR®   | Effective Nov. 26 <sup>th</sup> , 2019   |
| iES28G  | iES28GF-L2 or iES28TG-L2 | Effective Nov. 26 <sup>th</sup> , 2019   |
| iES20G  | iES20GF                  | Effective Nov. 26 <sup>th</sup> , 2019   |
| VDSL support on iTS12GP Card type Ethernet Switch | N/A                      | Effective Nov. 26, 2019, iTS12GP will be still available but without VDSL support. |
| 2GCX Combo for iRBX                               | 2GSFP                    | Effective Nov. 26 <sup>th</sup> , 2019   |
| iES28GP   | RAPTOR® – PoE            | Effective Feb. 18 <sup>th</sup> , 2020   |
| iES12GP   | iSG18GFP                 | Effective Aug. 7 <sup>th</sup> , 2020  |
| iES6-S  | iES8-S / iES6-SFP        | Effective Oct. 22 <sup>nd</sup> , 2020   |
| iMC2F   | iMC4F                    | Effective Dec 21 <sup>st</sup> , 2020  |
| SFP100BIDI1-SM-20 and SFP100BIDI2-SM-20           | N/A                      | Effective March 1 <sup>st</sup> , 2021   |
| iDS24GF   | Serial card on RAPTOR®   | Effective March 17 <sup>th</sup> , 2021  |
| SFP100-SGMII-MM                                   | N/A                      | Effective Sept 8 <sup>th</sup> , 2021  |
| iES12G  | iMR320/iES22GF           | Effective Sept 8 <sup>th</sup> , 2021  |
| iDS6  | iDS6P                    | Effective Sept 6, 2022   |
| iDS6P-S   | iMR320                   | Effective June 30, 2023  |
| iSG18GFP  | N/A                      | Effective Feb. 1 <sup>st</sup> , 2023  |

i5 Communications will continue to support the above discontinued products purchased through the Five-Year Warranty and provide ongoing Technical Phone Support. Return Manufacturing Authorization (RMAs) of discontinued products will be repaired and or replaced with an equivalent or higher-grade product within the Warranty period where applicable.

Please feel free to contact your Regional Sales Manager or i5Com Technical Support via e-mail [support@is5com.com](mailto:support@is5com.com) and/or by phone on our toll free number +1 844-520-0588, should you have any further questions.